

Look before you leap!

Ideally, conditions are dry and visibility is good, but the old adage still applies — look before you... **(Of course, you should *never* leap!)** Always use three points-of-contact to exit your vehicle.

Check for:

- Slick spots - snow, ice, oil or grease.
- Debris.
- Potholes or uneven ground.
- On-coming traffic.

Wear:

- Footwear appropriate for the weather and your work.
- Your high-visibility clothing.

Slow down and take the time to be safe.

You are worth more than your delivery!



www.KeepTruckingSafe.org